
Pipe Graphic Report of PLR S07KK1013MH X for Baltimore City


Setup	235 Surveyor	ADS-JF	RE	Certi	ficate #	: U-1204-1862	2 Syst	em Owner	BALTIMORE	CITY DPW
Draina	ge HL-39	Survey	Customer	C0139						
P/O #	07KK1	Date	2007/05/22	Time	9:42	Street C	DAKMONT AV	E 3701		
City	BALTIMORE		Furthe	r locatior	n details	s				
Start	S07KK1013MH		Rim to	invert	6.60	Grade to in	vert	Rim to gr	rade	Ft
Finish	S07KK1012MH		Rim to	invert	8.00	Grade to in	vert	Rim to gr	rade	Ft
Use S	anitary		Direct	i on Dow	/nstream	Flow cont	rol Not Cont	rolled	Media No	HL-C019
Shape	Circular		Heig	ght 8	Width	ins Pr	eclean J		Year Cleane	t
Materia	Vitrified Clay Pip	ре	Joi	nt length	3.0	Ft Total le	ngth 475.3	Ft Leng	th Surveyed	475.34
Lining			Ye	ar laid		Year rehabilita	ated	Weather	Dry	
Purpos	e Routine Assess	ment				Cat				
Additio	nal info						Structui	ral O8	kM (Constructional
Location	n Light Highway						Miscella	aneous Hy	draulic	





Pipe Graphic Report of PLR	S07KK1013MH	Χ	for	Baltimore City
po di apino itoport oi i zit	00711111111111	, ,		Daitin Toro Oity


Setup	235 Surveyor	ADS-JRE	Cert	ificate #	U-1204-1862	System Ow	ner BALTIMOF	RE CITY DPW
Drainaç	ge HL-39	Survey Cus	tomer C0139					
P/O #	07KK1	Date 20	07/05/22 Time	9:42	Street OAKN	MONT AVE 3701		
City	BALTIMORE		Further location	n details				
Start	S07KK1013MH		Rim to invert	6.60	Grade to invert	Rim	to grade	Ft
Finish	S07KK1012MH		Rim to invert	8.00	Grade to invert	Rim	to grade	Ft
Use S	anitary		Direction Dov	wnstream	Flow control	Not Controlled	Media No	HL-C019
Shape	Circular		Height 8	Width	ins Precle	an J	Year Clear	ned
Materia	Vitrified Clay Pip	e	Joint lengtl	h 3.0	Ft Total length	475.3 Ft	Length Survey	ed 475.34
Lining			Year laid	Υ	ear rehabilitated	Weathe	e r Dry	
Purpos	e Routine Assessi	ment			Cat			
Additio	nal info					Structural	O&M	Constructional
Location	n Light Highway					Miscellaneous	Hydraulic	





Pipe Graphic Report of PLR	S07KK1013MH	Χ	for	Baltimore City
pc diapine itopert of . =it	007111101011111	, ,		Daitin Toro Oity

Setup	235 Surveyor	ADS-JF	RE	Certi	ficate #	# U-1204-18	862	System O	wner BALTIM	ORE CITY DPW
Drainag	je HL-39	Survey	Customer	C0139						
P/O #	07KK1	Date	2007/05/22	Time	9:42	Street	OAKN	MONT AVE 3701		
City	BALTIMORE		Furthe	r locatio	n detail	s				
Start	S07KK1013MH		Rim to	invert	6.60	Grade to	invert	Rim	to grade	Ft
Finish	S07KK1012MH		Rim to	invert	8.00	Grade to	invert	Rim	to grade	Ft
Use Sa	anitary		Direct	ion Dov	vnstrear	n Flow co	ntrol	Not Controlled	Media N	o HL-C019
Shape	Circular		Heig	ght 8	Width	ins	Precle	an J	Year Cle	eaned
Materia	Vitrified Clay Pip	ре	Jo	int lengtl	3 .0	Ft Total	length	475.3 Ft	Length Surve	eyed 475.34
Lining			Ye	ar laid		Year rehabil	itated	Weath	ner Dry	
Purpos	e Routine Assess	ment				Cat				
Additional info Structural O&M Constru							Constructional			
Locatio	n Light Highway							Miscellaneous	Hydraulic	





Pipe Graphic Report of PLR S07KK1013MH X for Baltimore City

Setup	235 Surveyor	ADS-JRE		Certificate #	t U-1204-1862	System Ow	ner BALTIMO	RE CITY DPW
Draina	ge HL-39	Survey C	ustomer C01	39				
P/O #	07KK1	Date 2	2007/05/22	Time 9:42	Street OA	KMONT AVE 3701		
City	BALTIMORE		Further loc	ation detail	s			
Start	S07KK1013MH		Rim to inv	ert 6.60	Grade to inve	rt Rim	to grade	Ft
Finish	S07KK1012MH		Rim to inv	ert 8.00	Grade to inve	rt Rim	to grade	Ft
Use S	anitary		Direction	Downstream	Flow control	Not Controlled	Media No	HL-C019
Shape	Circular		Height	8 Width	ins Prec	lean J	Year Clea	aned
Materia	I Vitrified Clay Pip	ре	Joint le	ength 3.0	Ft Total lengt	th 475.3 Ft	Length Survey	yed 475.34
Lining			Year la	id	Year rehabilitate	d Weath	er Dry	
Purpos	e Routine Assess	ment			Cat			
Additio	nal info	·				Structural	O&M	Constructional
Location	n Light Highway					Miscellaneous	Hydraulic	

